**S**afety Page 1 of 7

**D**ata

**S**heet

#### 1. PRODUCT AND COMPANY IDENTIFICATION:

PRODUCT NAME: HiLo Silver Brazing Electrode (10690, 10691, 10790, 10791)

**DISTRIBUTOR:** Tifco Industries, Inc.

> PO Box 40277 Houston, TX 77240 Phone: 281-571-6000

EMERGENCY TELEPHONE NUMBER: Chem-Tel: 800-255-3924

#### 2. HAZARD IDENTIFICATION:

Emergency Overview: This product is normally not considered hazardous as shipped. Avoid eye contact or inhalation of dust from the product. When this product is used in a welding process, the most important hazards are welding fumes and heat.

Classification of the Substance/Mixture

CLP/GHS Classification (1272/2008):

Skin Irritation, Category 2 Eye Irritation, Category 2A

Hazardous to the Aquatic Environment – Acute Hazard, Category 1

# EU Classification (67/548/EEC):

Irritant (Xi), Dangerous for the Environment (N), R36/37/38, R50

### Labeling:





Signal Word: Warning **Hazard Statements:** 

H315 - Causes skin irritation.

**H319** – Causes serious eye irritation.

**H400** – Very toxic to aquatic life.

#### **Precautionary Statements:**

**P210** – Keep away from heat/sparks/open flames/hot surfaces – No smoking.

**P264** – Wash skin and hair thoroughly after handling.

**P273** – Avoid release to the environment.

**P280** – Wear gloves/eye protection/face protection.

P302+P352 - IF ON SKIN: Wash with plenty of soap and water.

P305+P351+P338 – IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.

P332+P313 – IF skin irritation occurs: Get medical advice/attention.

P337+P313 – IF eye irritation persists: Get medical advice/attention.

**P362** – Take off contaminated clothing and wash before reuse.

**P391** – Collect spillage.

**P501** – Dispose of contents/container in accordance with local/regional/national/international regulations.

Page 2 of 7

**S**afety **D**ata

**S**heet

# 3. COMPOSITION / INFORMATION ON INGREDIENTS:

Chemical Identity	CAS#	Range %	OSHA PEL (mg/m3)	ACGIH-TLV (mg/m3)	Carcinogenicity	EU Classification (67/548/EEC)	CLP/GHS Classification (1272/2008)
Tin	7440-31-5	1-11	2	2	No	Not Dangerous	Not Hazardous
#Silver	7440-22-4	12-35	.01	.1	No	Not Dangerous	Not Hazardous
#Copper	7440-50-8	13-24	1.0	1.0	No	(F) R11	(H228) Flam. Sol. 1
						(N) R50	(H400) Aquatic Acute 1
#Zinc	1314-13-2	6-13	5.0	5.0	No	(N),R50/53	(H400) Aquatic Acute 1
							(H410) Aquatic C. 1 🧇
Potash	584-08-7	1-11	NR	NR	No	<b>X</b> (Xn) R22	(H302) Acute Tox. 4 <
							(H315) Skin Irrit 2 <
						(Xi) R36/37/38	(H319) Eye Irrit 2A 📀
							(H335) STOT SE 3 <
Potassium	14075-53-7	15-25	2.5 (as F)	2.5 (as F)	No	<b>X</b> (Xn) R22	(H302) Acute Tox. 4 <>>
Fluorborate							(H315) Skin Irrit 2 🔷
						(Xi) R36/38	(H319) Eye Irrit 2A <>>
Potassium	12045-78-2	1-11	15	10	No	90	(H314) Skin Corr. 1B 🔷
Tetraborate						(C) R34	
Boric Acid	10043-35-3	1-11	15	10	No	Repr. Cat. 2	(H360FD) Repr. 1B
						(T),R60, R61	, , , ,

Important This section covers the materials of which the products manufactured. The fumes and gases produced during normal use of this product are covered in section 10. The term "Hazardous" in "Hazardous Material" should be interpreted as a term required and defined in OSHA Hazard Communication Standard 29CFR 1910-1200 and it does not necessarily imply the existence of hazard. The chemicals or compounds reportable by Section 313 of SARA are marked by the symbol #.

#### 4. FIRST AID MEASURES:

**Inhalation**: Remove to fresh air immediately or administer oxygen. Get medical attention immediately.

**Skin**: Flush skin with large amounts of water and soap. If irritation develops and persists, get medical attention.

**Eye:** Flush eyes with water for at least 15 minutes. Get medical attention. **Ingestion:** Obtain medical attention immediately if ingested. Rinse mouth.

#### 5. FIRE-FIGHTING MEASURES:

Suitable Extinguishing Media: Not applicable. Non-combustible; inherent fire retardant.

Unsuitable Extinguishing Media: Not applicable

Specific Hazards Arising From Chemical: 29 CFR 1910.120 (Non Flammable Solid). Boric oxide fumes.

Tin oxides, Copper oxides, Carbon oxides, Zinc/zinc oxides, Borane/boron oxides, Potassium oxides, Silver/silver oxides

Protective Equipment: Fire fighters should wear complete protective clothing including self-contained breathing apparatus.

#### 6. ACCIDENTAL RELEASE MEASURES:

**Personal Precautions:** Refer to section 8. **Environment Precautions:** Refer to section 13.

**Cleaning Measures:** Collect mechanically. Solid objects may be picked up and placed into a container. Liquids or paste should be scooped up and placed into a container. Wear proper protective equipment while handling these materials. Do not discard as refuse.

#### 7. HANDLING AND STORAGE:

**Precautions for Safe Handling:** Handle with care to avoid stings or cuts. Wear gloves when handling welding consumables. Avoid exposure to dust. Do not ingest. Some individuals can develop an allergic reaction to certain materials. Retain all warning and identity labels.

**Conditions for Safe Storage:** Store in dry place in closed packages. Keep separate from chemical substances like acids and strong bases, which could cause chemical reactions.

Page 3 of 7

**S**afety **D**ata

**S**heet

#### 8. EXPOSURE CONTROLS/ PERSONAL PROTECTION:

**Engineering Controls:** The usual precautionary measures for handling chemicals should be followed. Keep away from food, beverages and feed. Remove all soiled and contaminated clothing immediately. Wash hands before break and at the end of the work. Store all protective clothing separately. Maintain an ergonomically appropriate working environment. Wear protective equipment. Keep unprotected persons away. Avoid causing dust.

**Exposure limits:** Use industrial hygiene equipment to ensure that exposure does not exceed applicable national exposure limits. The limits defined under section 3 can be used as guidance. Unless noted, all values are for 8 hour time weighted average.

Biological limits: No available data

Personal protection:

**Respiratory protection:** Use an air purifying dust respirator when welding or brazing in a confined space, or when local exhaust or ventilation is not sufficient to keep exposure values within safe limits.

**Hands protection:** Wear appropriate gloves to prevent skin contact.

EN 12477: Protection gloves for welders

Requirements (EN Levels)	Type A	Type B
Abrasion (Cycles)	2 (500)	1 (100)
Cut (Factor)	1 (1.2)	1 (1.2)
Tear (Newton)	2 (25)	1 (10)
Puncture (Newton)	2 (60)	1 (20)
Burning Behavior	3	2
Contact Heat	1	1
Convective Heat	2	-
Small Splashes	3	2
Dexterity	1 (11)	4 (6.5)

Type B gloves are recommended when high dexterity is required as for TIG welding, while type A gloves are recommended for other welding processes. The contact temp (°C) is 100 and the threshold time (seconds) >15.

**Eyes protection:** Welder's helmet or face shield with color absorbing lenses. Shield and filter to provide protection from harmful UV radiation, infra red and molten metal approved to standard EN379. Filter shade to be a minimum of shade 9.

**Skin protection:** Heat-resistant protective clothing. Wear safety boots, apron, arm and shoulder protection. Keep protective clothing clean and dry. Clothing should be selected to suit the level, duration and purpose of the welding activity.

	Class 1		
Impact of Spatter	15 Drops		
Heat Transfer (radiation) RHTI 24 ≥ 7 seconds			
Process	Manual welding with light formation of spatter and drops     Gas Welding     TIG Welding     MIG Welding     Micro plasma welding     Brazing     Spot Welding     MMA Welding (with rutile-covered electrode)		
Environmental Conditions	Operation of machines     Oxygen cutting machines     Plasma cutting machines     Resistance welding machines     Machines for thermal spraying     Bench welding		

**S**afety **D**ata

Sheet

# Page 4 of 7

	Class 2		
Impact of Spatter	25 Drops		
Heat Transfer (radiation)	RHTI 24 ≥ 16 seconds		
Process	Manual welding with heavy formation of spatter and drops		
	<ul> <li>MMA welding (with basic or cellulose-covered electrodes)</li> </ul>		
	MAG welding (with CO2 or mixed gases)		
	MIG Welding (with high current)		
	Self shielded flux core arc welding		
	Plasma cutting		
	Gouging		
	Oxygen cutting		
	Thermal spraying		
Environmental Operation of machines			
Conditions	<ul> <li>In confined spaces</li> </ul>		
	<ul> <li>At overhead welding/cutting or in comparable constrained positions</li> </ul>		

## 9. PHYSICAL AND CHEMICAL PROPERTIES:

Appearance: Solid

Color: None/3137- orange/ 3140- none/ 3147- orange/ 3155- pink/ 3157- none

Odor: Odorless

Odor Threshold: Not Available pH Value: Not Available Specific Gravity: Not Available

Melting Point/Melting Range: 1560-2000° F, 850-1100° C

Freezing Point: Not Available

Boiling Point/Boiling Range: Not Available

Flash point: Not Available
Evaporation Rate: Not Available
Self-in flammability: Not Available
Explosion limits: Not Available
Vapor pressure: Not Available
Vapor density: Not Available
Density at 20°C: Not Available
Relative density: 6-9 g/cm3
Solubility: Insoluble in water.
Partition coefficient: Not Available
Auto-ignition temperature: Not Available
Decomposition temperature: Not Available
Other Information: No available data.

#### 10. STABILITY AND REACTIVITY:

**Chemical Stability:** This product is stable under normal conditions. This product loses H2O when heated. **Hazardous Reactions:** Contact with chemical substances like acids or strong bases cause generation of gas.

Conditions to Avoid: Not applicable.

**Incompatible Materials:** Oxidizing agents. Reaction with strong reducing agents such as metal hydrides, acetic anhydride or alkali metals will generate hydrogen gas which could create an explosive hazard.

Hazardous Decomposition Products: Boric oxide fumes.

# 11. TOXICOLOGICAL INFORMATION:

Acute Effects: Overexposure to brazing and soldering fumes may result in symptoms like metal fume fever, dizziness, nausea, dryness or irritation of the nose, throat or eyes. Tin: May cause skin irritation. May cause eye irritation due to

mechanical action. Inhalation of tin dust may cause respiratory tract and mucous membrane tract irritation due to mechanical

Page 5 of 7

**S**afety **D**ata

# **S**heet

action. It is poorly absorbed from the digestive tract. It can cause gastrointestinal tract disturbance which may be irritant or astringent on the stomach. Silver may cause argyria (a slate-grey or bluish discoloration of the skin and deep tissues due to the deposit of insoluble albuminate of silver). Symptoms of systematic copper poisoning may include: capillary damage, headache, cold sweat, weak pulse, kidney and liver damage, central nervous system excitation followed by depression, jaundice, convulsions, paralysis and coma. Signs and symptoms of zinc exposure are central nervous system depression, cough, chest pain and difficulty breathing. Exposure to high airborne concentrations can cause anesthetic effects. Toxicity reported for borates in humans: ingestion or absorption may cause nausea, vomiting, diarrhea, abdominal cramps, anderythematous lesions on the skin and mucous membranes. Other symptoms include: circulatory collapse, tachycardia, cyanosis, delirium, convulsions and coma. Death has been reported to occur in infants from less than 5 grams and in adults from 5 to 20 grams.

LD/LC50 Values that are relevant for classification		
Silver 7440-22-4		
Oral LD50 >5000 mg/kg (rat)		

LD/LC50 Values that are relevant for classification		
Copper 7440-50-8		
Oral	LD50	>2000 mg/kg (rat)
Dermal	LD50	>2000 mg/kg (rat)
Inhalation	LC50	>5.11 mg/L/4 hr (rat)
Intraperitoneal	LD50	3.5 mg/kg (mouse)

LD/LC50 Values that are relevant for classification		
Zinc 7440-66-6		
Oral LD50 630 mg/kg (rat)		

LD/LC50 Values that are relevant for classification			
Potassium Carbonate 584-08-7			
Oral LD50 1870 mg/kg (rat)			
LC50 <510 mg/l (96h) (fathead minnow)			

LD/LC50 Values that are relevant for classification			
Boric Acid 10043-35-3			
Oral	LD50	2660 mg/kg (rat)	
LC50 53.2 mg/l (21d) (water flea)			

**Chronic Effects:** Overexposure to brazing and soldering fumes may affect pulmonary function. Chronic copper poisoning is typified by hepatic cirrhosis, brain damage and demyelination, kidney defect and copper deposition in the cornea as exemplified by humans with Wilson's disease. It has also been reported that copper poisoning has led to hemolytic anemia and accelerates arteriosclerosis, damage to the lungs, vomiting, diarrhea, abdominal pain and blood disorders. Excessive inhalation of zinc oxide fumes may produce symptoms known as "Zinc Shakes" which are flu-like and usually cease when the individual is removed from the source. Prolonged or repeated exposure can cause vomiting, diarrhea, lung irritation.

# 12. ECOLOGICAL INFORMATION:

Toxicity: No available data.

Persistence and Degradability: No available data. Bio accumulative Potential: No available data.

Mobility in Soil: No available data.

Other Adverse Effects: No available data.

Do not allow undiluted product or large quantities to reach ground water, water course or sewage systems. Do not allow product to be released in the environment without proper governmental permits.

Page 6 of 7

**S**afety

**D**ata

**S**heet

#### 13. DISPOSAL CONSIDERATIONS:

**Product:** For product elimination, dispose of in accordance with EPA regulations.

**Package:** May be disposed in approved landfills provided local regulations are observed.

14. TRANSPORT INFORMATION:

**UN-number:** Not applicable

**UN proper shipping name:** Not applicable **Transport hazard class:** Not applicable

Packing group: Not applicable

**Environmental hazards:** Not applicable **Special precautions for users:** Not applicable

#### 15. REGULATORY INFORMATION:

**Safety, health and environment regulations/legislation specific for the substance or mixture:** Read and understand the manufacturer's instructions, your employer's safety practices and the health and safety instructions on the label. Observe any federal and local regulations. Take precautions when welding and protect yourself and others.

**Warning:** Welding fumes and gases are hazardous to your health and may damage lungs and other organs. Use adequate ventilation. Electric shock can kill. Arc rays and sparks can injure eyes and burn skin. Wear correct hand, head, eye and body protection.

#### Chemical safety assessment: No

USA: Under the OSHA Hazard Communication Standard, this product is considered hazardous. This product contains or produces a chemical known to the state of California to cause cancer and birth defects (or other reproductive harm). (California Health & Safety Code § 25249.5 et seq.) United States EPA Toxic Substance Control Act: All constituents of this product are on the TSCA inventory list or are excluded from listing.

#### **EPCRA/SARA Title III Toxic Chemicals**

The following metallic components are listed as SARA 313 "Toxic Chemicals" and potential subject to annual SARA reporting. See Section 3 for weight percentage.

Ingredient Name	Disclosure Threshold
Silver	.01 mg/m3
Copper	1.0 mg/m3
Zinc	5.0 mg/m3

#### 16. OTHER INFORMATION:

The information in this document is believed to be correct as of the date issued. However, no warranty is expressed to be implied regarding the accuracy or completeness of this information. This information and product are furnished on the condition that the person receiving them shall make his own determinations as to the suitability of the product for his particular purpose and on the condition that he assumes the risk of his use thereof.

This Material Safety Data Sheet complies with the EC directives 91/155/EEC and 93/112/EEC, including modifications 2001/58/EC.

Complies with OSHA Communication Standard 29 CFR 1910.1200 and Superfund Amendments and Reauthorization Act (SARA) of 1986 Public Law 99-499

Hazard Statements: H228 -

Flammable solid. H302 -

Harmful if swallowed.

H314 – Causes severe skin burns and eye damage.

H315 - Causes skin irritation.

H319 - Causes serious eye irritation.

**H335** – May cause respiratory irritation.

H360- May damage fertility or the unborn child.

**H400** – Very toxic to aquatic life.

**H410** – Very toxic to aquatic life with long lasting effects.

# Safety Page 7 of 7

# **S**heet

**D**ata

#### R-Phrases:

R11 - Highly flammable.

R22 - Harmful if swallowed.

R34 – Causes burns.

R36/38 - Irritating to eyes and skin.

R36/37/38 – Irritating to eyes, respiratory system and skin.

R50 - Very toxic to aquatic organisms.

R50/53 – Very toxic to aquatic organisms, may cause long-term adverse effects in the aquatic environment.

R60 - May impair fertility.

R61 - May cause harm to the unborn child. S-

#### Phrases:

**S16** – Keep away from source of ignition – No smoking.

**S26** – In case of contact with eyes, rinse immediately with plenty of water and seek medical advice.

**\$36/37/39** – Wear suitable protective clothing, gloves and eye/face protection.

**S45** – In case of accident or if you feel unwell, seek medical advice immediately (show the label where possible).

**\$53** – Avoid exposure – obtain special instructions before use.

**S61** – Avoid release to the environment.

.

End of the document.